


The gas pressure gauge is of 0-5 bar range  
 DN20 M27\*1.5 gas line extends to the gas joint of dryer equipment  
 The gas high-pressure to medium pressure valve requires the output pressure of 0.9-1.1BAR, which can be adjusted manually. The flow rate is 20KG /H.  
 Models: MESURA TYPE: M64R, D200R are recommended



Reserved link gas bottle can bend pipe joints at will

best choose 1 inch steel tube, can not use any non-metallic tube



When in use, make sure both bottles of gas are working at the same time